Founder and Path-Darshak Late Shri J.J.VAGHELA

MAYOOR J. VAGHELA

BE, DIS, PGDIEM, MISNT, MIE, FIV Competent Person, Chartered Engineer Safety Professional, Appr. Valuer Mobile: 99241 24196

An ISO 9001: 2015 Company **DISH Approved Training Institute**

INDUSTRIAL SAFETY, FIRE, HEALTH & ENVIRONMENT PROFESSIONALS, COMPETENT PERSONS



F-22 & 25, Vardhaman Complex, Subhanpura Main Road, VADODARA - 390 023. Gujarat, INDIA. Office Mobile: 9428300096, 6355441934 E-mail: helpsisp@gmail.com Website: www.helpssafetyconsultant.com

Ref No. HELPS/CE/JJIS/2023

Dtd. 15.06.2023

Certificate of Stability for Continued Use of School

1. Name of the Building

Jay Jalaram International School, Anand (Managed

by Shivmani Charitable Trust)

Address

Beside Essar Petrol Pump, Anand - Lambhvel Road, Tal.

Anand. Dist. Anand - 388001

Phone No. / E-mail

Jjisanand@gmail.com

4. Name of the Occupier

of the Premises

Shivmani Charitable Trust, Vikas Gupta

6. No. of floors

Basement, Ground Floor, First Floor, Second Floor, Third

Floor

I certify that, I have inspected the premises on 15.06.2023, based on physical inspection of the premises. I am of the opinion that the structure of the said premises appears in sound condition and that its / their stability will not be endangered by its continued use for which the building was intended.

Place: Vadodara

Date: 15th June, 2023

Signature:

MIE, MISNT, FIV M / 131162 / 4

Name in Block Letter: MAYOOR J. VAGHELA

Encl : School Survey Form

Ref. No. of Corporate:

Membership

M 131162/4

Designation

: Chartered Engineer

School Survey Form

1.	School Name	Jay Jalaram International School, Anand
2.	School ID	
3.	School Category (Pre-Primary-A, Primary-B, Secondary-C, Higher Secondary-D)	A, B, C & D
4.	Address	
	a). Location	Beside Essar Petrol Pump, Anand- Lambhvel Road, Tal. Anand, Dist. Anand - 388001
	b). Village /Town / City :	Anand
	c). Census Code :	
	d). Taluka :	Anand
	e). District :	Anánd
	f). Nearest Town	Anand
5.	GPS Coordinates of School (Any centre Point)	22°34'22.31"N 72°56'31.05"E
6.	Communication System	Telephone, Mobile
7.	School Area (meter square)	
i.	a). Plot Area :	5100.00 Sq. mtr
	b). Footprint Area :	1217.54 Sq. mtr
	c). Built up Area :	4870.16 Sq. mtr
8.	Number of (indicate as per shifts if any)	
	a). Pupils	
	b). Teachers	
	c). Other Staff	
	d). Physically challenged Staff	7
9.	Number of Rooms	
	a). Class Rooms	
	b). Other Rooms	



School Survey Form Continue...

	<u>C0</u>	ntinue
10.	Number of stories :	
N X	a). Basement (Yes / No)	Yes
	b). Stories	Three
	c). Mezzanine (Yes / No)	No
11.	Typical Storey height (m)	fire in the second seco
12.	Stilt at Ground Floor : (Yes / No)	17 y
13.	Type of Load carrying system :	
	a). Stone Masonry Bearing walls	
	b). Brick Masonry Bearing walls	
	c). RCC Frames	RCC Frame structure
	d). Steel Structure	
	e). Other (elaborate)	
14.	Partition walls : Reinforced Concrete/ wood / Masonry / Mixed / Other (Specify)	Brick Masonry
15.	Floor Slabs : Reinforced Concrete / wood / Other (Specify)	Reinforced Concrete slab
16.	Floor Finish : Wood / Ceramic / Mosaic / IPS/ other (Specify)	Ceramic Tiles
17.	Roof: Reinforced Concrete Flat roof / Reinforced Concrete sloping roof / wood / Asbestos / Metal Sheets / Other (Specify)	Reinforced Concrete Flat roof
18.	Seismic / other disaster safety features in the building (in case of masonry)	NA
	a). Plinth Band	
9 9 10 10	b). Lintel Band	
	c). Roof Band	
	d). Other Features	



School Survey Form Continue...

19	Seismic / other disaster safety features in the building (in case of RC frame)	
	a). Proper framing grid of more than 3 frames of min 3 bays in both direction	Yes
	b). Max cantilever projection (m)	Front
1 1	c). Any floating columns ? if yes, give details	No
20	Quality of Building	
	a). Workmanship	5
	b). Maintenance Grade on a scale of 5) (5 of excellent and 1 for poor)	5
19.	Any existing visible damages (Yes/No) If yes : Description	No
20.	Last repair & reconstruction work a). Repaired (Year) b). Strengthened (Year)	NA
21.	Fire Protection (Yes / No)	
	a). High voltage electric transformers not protected within campus or 25m periphery of school	
	b). Loose electric wires within campus and not fenced	
	c). Any highly flammable / Hazardous goods lying in the school or surrounding buildings	
	d). Petrol Pump (25 m periphery of school)	Yes
	e). Hydrants (Yes / No)	1 - 4 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
	f). Fire Extinguishers (Yes / No)	Yes
	g). Fire Alarms (Yes / No)	
	h). Smoke detectors (Yes / No)	



School Survey Form

9	Con	tinue
22.	Surrounding of School	
	a). High Rise / low Rise Buildings	Low Rise
	b). Congested / Market Area	
	c). High documentation available	4
23.	Technical documentation available	The state of the s
N.	a). Architecture (Yes / No)	Yes
	b). Structural Design (Yes / No)	Yes
24.	Site - Soil conditions : Rock / Firm / Medium / Soft	Firm
25.	Slope : Flat / Slight Slope : Moderate Slope : Sleep slop	Flat
26.	Seismic exposure : (To be filled by reviewing Engineer) a). Seismic Zone b). Unknown	III
Re V	History of Disaster (Mention month, year, frequency and damages due to the disaster)	
27.	a). Earthquakeb). Cyclonec). Floodsd). Fire	
28.	Awareness in School a). Among Teachers b). Among Students c). Any formal course / Training for disasters	
29.	Preparedness for Disasters a). Contingency Plan b). Escape Routes c). Safe Shelters during Cyclone d). Other Preparedness	
30.	Photographs	
31.	Remark & recommendations (Yes / No)	No

Surveyor

Name: Mayoor J. Vaghela

Signature:

Date: 15.06.2023

BE,DIS,PGDIEM MIE, MISNT,FIV M / 131162 / 4 Principal

Name:

Debjani Lahiri Principal

Jay Jalaram International School, Anand

Signature :

Building ID

(Line Plan of the School Campus and Building IDs)